Part I: Summary							
PHA Name : CHARLESTON CO HSG & REDEV AUTH PHA Number: SC056		Locality (City/Co X Original 5-Ye	•	Revised 5-Year I	Plan (Revision No:)	
А.	Development Number and Name	Work Statement for Year 1 2017	Work Statement for Year 2 2018	Work Statement for Year 3 2019	Work Statement for Year 4 2020	Work Statement for Year 5 2021	
	SINGLE FAMILY UNITS (SC056000235)	\$148,756.80	\$160,756.80	\$155,756.80	\$160,756.80	\$160,756.80	
	AUTHORITY-WIDE	\$246,851.20	\$246,851.20	\$246,851.20	\$246,851.20	\$246,851.20	
	JOSEPH FLOYD MANOR (SC056000001)	\$27,000.00	\$15,000.00	\$20,000.00	\$15,000.00	\$15,000.00	
	BRIGHTON PLACE (SC056000007)	\$8,500.00	\$8,500.00	\$8,500.00	\$8,500.00	\$8,500.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 1 2017			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
SINGLE FAMILY UNITS (SC056000235)			
Roof Replacements(Dwelling Unit-Exterior (1480)-Roofs)		\$72,000.00	
Replace Kitchen Cabinets(Dwelling Unit-Interior (1480)-Kitchen Cabinets)		\$10,000.00	
Replace Flooring(Dwelling Unit-Interior (1480)-Flooring (non routine))		\$31,756.80	
Raise Foundation(Dwelling Unit-Exterior (1480)-Foundations)		\$17,000.00	
Windows(Dwelling Unit-Exterior (1480)-Windows)		\$5,000.00	
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$13,000.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 1 2017			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
JOSEPH FLOYD MANOR (SC056000001)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$15,000.00	
Security Cameras(Dwelling Unit-Interior (1480)-Other)		\$12,000.00	
BRIGHTON PLACE (SC056000007)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$8,500.00	
Subtotal of Estimated Cost		\$184,256.80	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 2 2018			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
SINGLE FAMILY UNITS (SC056000235)			
Roof Replacements(Dwelling Unit-Exterior (1480)-Roofs)		\$72,000.00	
Replace Kitchen Cabinets(Dwelling Unit-Interior (1480)-Kitchen Cabinets)		\$10,000.00	
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$18,000.00	
HVAC Replacements(Dwelling Unit-Exterior (1480)-Other)		\$60,756.80	
JOSEPH FLOYD MANOR (SC056000001)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$15,000.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 2 2018			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
BRIGHTON PLACE (SC056000007)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$8,500.00	
Subtotal of Estimated Cost		\$184,256.80	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 3 2019			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
SINGLE FAMILY UNITS (SC056000235)			
Roof Replacements(Dwelling Unit-Exterior (1480)-Roofs)		\$72,000.00	
Replace Kitchen Cabinets(Dwelling Unit-Interior (1480)-Kitchen Cabinets)		\$10,000.00	
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$13,000.00	
HVAC Replacements(Dwelling Unit-Exterior (1480)-Other)		\$60,756.80	
JOSEPH FLOYD MANOR (SC056000001)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$20,000.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 3 20	019		
Development Number/Name General Description of Major Work Categories		Quantity	Estimated Cost
BRIGHTON PLACE (SC056000007)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)			\$8,500.00
Subtotal of Estimated Cost			\$184,256.80

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 4 2020			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
SINGLE FAMILY UNITS (SC056000235)			
Roof Replacements(Dwelling Unit-Exterior (1480)-Roofs)		\$72,000.00	
Replace Kitchen Cabinets(Dwelling Unit-Interior (1480)-Kitchen Cabinets)		\$15,000.00	
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$13,000.00	
HVAC Replacements(Dwelling Unit-Exterior (1480)-Other)		\$60,756.80	
JOSEPH FLOYD MANOR (SC056000001)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$15,000.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 4 2020			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
BRIGHTON PLACE (SC056000007)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$8,500.00	
Subtotal of Estimated Cost		\$184,256.80	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 5 2021			
Development Number/Name General Description of Major Work Categories	Quantity	Estimated Cost	
SINGLE FAMILY UNITS (SC056000235)			
Roof Replacements(Dwelling Unit-Exterior (1480)-Roofs)		\$72,000.00	
Replace Kitchen Cabinets(Dwelling Unit-Interior (1480)-Kitchen Cabinets)		\$15,000.00	
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$13,000.00	
HVAC Replacements(Dwelling Unit-Exterior (1480)-Other)		\$60,756.80	
JOSEPH FLOYD MANOR (SC056000001)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)		\$15,000.00	

Part II: Supporting Pages - Physical Needs Work Statements (s)			
Work Statement for Year 5	2021		
Development Number/Name General Description of Major Work Categories		Quantity	Estimated Cost
BRIGHTON PLACE (SC056000007)			
Replace Appliances(Dwelling Unit-Interior (1480)-Appliances)			\$8,500.00
Subtotal of Estimated Cost			\$184,256.80

Part III: Supporting Pages - Management Needs Work Statements (s)			
Work Statement for Year 1 2017			
Development Number/Name General Description of Major Work Categories	Estimated Cost		
Housing Authority Wide			
Operations(Operations (1406))	\$99,624.00		
Debt Service(Debt Service Bond Payment-Paid by HUD (9000))	\$110,227.20		
Administration(Administration (1410)-Sundry,Administration (1410)-Salaries)	\$37,000.00		
Subtotal of Estimated Cost	\$246,851.20		

Part III: Supporting Pages - Management Needs Work Statements (s)	
Work Statement for Year 2 2018	
Development Number/Name General Description of Major Work Categories	Estimated Cost
Housing Authority Wide	
Operations(Operations (1406))	\$99,624.00
Debt Service(Debt Service Bond Payment-Paid by HUD (9000))	\$110,227.20
Administration(Administration (1410)-Sundry,Administration (1410)-Salaries)	\$37,000.00
Subtotal of Estimated Cost	\$246,851.20

Part III: Supporting Pages - Management Needs Work Statements (s)	
Work Statement for Year 3 2019	
Development Number/Name General Description of Major Work Categories	Estimated Cost
Housing Authority Wide	
Operations(Operations (1406))	\$99,624.00
Debt Service(Debt Service Bond Payment-Paid by HUD (9000))	\$110,227.20
Administration(Administration (1410)-Salaries,Administration (1410)-Sundry)	\$37,000.00
Subtotal of Estimated Cost	\$246,851.20

Part III: Supporting Pages - Management Needs Work Statements (s)	
Work Statement for Year 4 2020	
Development Number/Name General Description of Major Work Categories	Estimated Cost
Housing Authority Wide	
Operations(Operations (1406))	\$99,624.00
Debt Service(Debt Service Bond Payment-Paid by HUD (9000))	\$110,227.20
Administration(Administration (1410)-Salaries,Administration (1410)-Sundry)	\$37,000.00
Subtotal of Estimated Cost	\$246,851.20

Part III: Supporting Pages - Management Needs Work Statements (s)	
Work Statement for Year 5 2021	
Development Number/Name General Description of Major Work Categories	Estimated Cost
Housing Authority Wide	
Operations(Operations (1406))	\$99,624.00
Debt Service(Debt Service Bond Payment-Paid by HUD (9000))	\$110,227.20
Administration(Administration (1410)-Sundry,Administration (1410)-Salaries)	\$37,000.00
Subtotal of Estimated Cost	\$246,851.20